



Preventive Maintenance Service Report

Customer Details		Service Ticket Details	
Customer ID	: 800000854661	Checklist No.	: 1063643
Name	: Daniel Issac	Channel Partner Type	: Channel Partner
Address	: B301 Raj Horizon Ramdev Park miraroad east Near Akash Nidhi Building M Mira Bhayandar, Maharashtra, 401107 India	Service Provider No.	: LI00238-02
Email Id	: santoshkemailbox@gmail.com	Service Provider Name	: INDO COOL
Mobile No.	: 7709574555		

Service Ticket Details						
Line No.	Ticket/Complaint No	Model No.	Product Serial No.	Component No.	UOM	SOL ID
1	A21070222987	BO-IC524DATX	BO-IC524DATXBTA00699	2000671057	Tonnage of Refrigeration-2.0	

WINDOW,HI-WALL,VERTICOOL & MEGA SPLIT UNITS

IDU	BO-IC524DATXBTA00699
1. Before start of service, apply Lock Out Tag Out (LOTO) in MCB to ensure disconnection of power supply	
2. Check and ensure all electrical wires connected in connector with Lugs & properly fastened in IDU & ODU	
3. Run the machine and check its smooth operation	
4. Check visible signs of oil / leakage	
5. Clean evaporator coils and drain Tray	
6. Clean air filters	
7. Check operation and position of room sensor	
8. Check drain line for leakage / clogging / Sweating	
9. Check for abnormal noise in blower / motor	
10. Check movement of Louvers	
11. Check Blue Star logo in place	
12. Ensure LOTO is removed & power is switched ON	
13. Grill temperature	12.00
14. Return air temperature	26.00
15. Room temperature	29.00
ODU	
1. Check visible signs of oil / leakage	
2. Check for undue vibrations in the compressor	
3. Check for abnormal noise in fan / motor	
4. Check tightness of all electrical connections	
5. Check all nut bolts / screws are in proper place	

Download the Blue Star Customer Care APP



For any query, please email us at : customerservice@bluestarindia.com

24/7 Customer Care No. : 1800 209 1177 SMS 'SERVICE to 57575

Visit us at www.bluestarindia.com

Registered Address

Blue Star Ltd. Kasturi Buildings, Mohan T Advani Chowk, Jamshedji Tata Road, Mumbai - 400 020, India.

Tel: +91 22 66654000 Fax: +912266654152 CIN:L28920MH1949PLC006870

6. Check the condition of vibration isolations	
7. Clean condenser coil with blower / water / Comb fins	
8. Check the structure for sturdiness	
9. Suction pressure (psig)	120
10. Discharge pressure (psig)	250
11. System input voltage on load (volts)	230
12. Compressor (amps)	
12.1 R	1.00
12.2 Y	0.00
12.3 B	0.00
13. Condenser motor amps	0.50
14. Ambient temperature	32.00

Attachments


21-Jul-2021 16:15:24

Technician's Remarks:

pms done

Customer Signature

Service Details



Report submission date : 21-Jul-2021
Service done by : LI00238-02-T0001 ARVIND
Mobile Number : 9823450144
Work Completed Date : 21-Jul-2021
Technician's Remarks : pms done

Download the Blue Star Customer Care APP



For any query, please email us at : customerservice@bluestarindia.com

24/7 Customer Care No. : 1800 209 1177 SMS 'SERVICE to 57575

Visit us at www.bluestarindia.com

Registered Address

Blue Star Ltd. Kasturi Buildings, Mohan T Advani Chowk, Jamshedji Tata Road, Mumbai - 400 020, India.

Tel: +91 22 66654000 Fax: +912266654152 CIN:L28920MH1949PLC006870

Customer/Site In-charge	: Daniel Issac	To know your real service site location, please copy & paste latitude and longitude number in to Google map: eg. (22.2909845,70.7886653) https://www.google.co.in/maps/place/19.2729121,72.8902817
Mobile No.	: 7709574555	
OTP sent mobile no.	: +917709574555	
Email Id	: santoshkmailbox@gmail.com	
Rating	: ★★★★★	
Customer's Remarks	: ok	

Download the Blue Star Customer Care APP



For any query, please email us at : customerservice@bluestarindia.com

24/7 Customer Care No. : 1800 209 1177 SMS 'SERVICE to 57575

Visit us at www.bluestarindia.com

Registered Address

Blue Star Ltd. Kasturi Buildings, Mohan T Advani Chowk, Jamshedji Tata Road, Mumbai - 400 020, India.

Tel: +91 22 66654000 Fax: +912266654152 CIN:L28920MH1949PLC006870